

## Wall: version 1



2. Connect ethernet cable with product, then attach product to the mount.

3. When the product is attached on the mount, pull it down until it snaps into place.

Wall: version 2



2. Connect ethernet cable [1] with product, then attach product to the mount.

3. When the product is attached on the mount, pull it down until it snaps into place.

## Ceiling



2. Insert ethernet cable [1] through sheet metal loop and drill hole. Connect cable with product [2]. Attach on the mount [3].



## cAP XL ac mounting instruction

All pictures shown are for illustration purpose only

3. When the product is attached on the mount, push it in showing direction